



Lead Service Line Inventory Template

*Please enter information in the empty box next to each section		Water System Name		Girard		System ID Number:		1170450		Current Inventory Date:		6/2/2026	
*Please enter totals in the empty box next to each category		Total Service Lines:		913		Total Lead:		0		Total Non-Lead:		601	
						Total Galvanized Requiring replacement:		3		Total Unknown:		309	
										Website link to Material Inventory:		LINK TO FOLLOW WITH SUBMISSION	

Service Address	Lead and Copper Sample ID# number.	Is this a High-Risk Facility or Area?	Service Line Newly Identified from Lead Service Line Inventory	Year PWS Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Figtal	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entry Service Line	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Refusal or Date notified, if customer refused access to property	
EXAMPLES		EXAMPLES		EXAMPLES		EXAMPLES		EXAMPLES		EXAMPLES		EXAMPLES		EXAMPLES		EXAMPLES		
	Lead and Copper Sample ID# number starting with "LP" or "LA" / "L" / "N/A" If address is not a lead and copper sample site mark "N/A"	Group Homes, Parks, Prisons, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line identified? Construction Records, Visual Inspection, Survey Response, Maintenance Records, etc.	Galvanized (G) Lead (L) Cast/Ductile Iron or Titanium (D) Plastic - PVC, HDPE, PEK (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CS) Galvanized (G) Lead (L) Cast/Ductile Iron or Titanium (D) Plastic - PVC, HDPE, PEK (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CS) Galvanized (G) Lead (L) Cast/Ductile Iron or Titanium (D) Plastic - PVC, HDPE, PEK (P) Unknown (U) Unknown Not Lead (UNL)	Copper - Lead Solder (CS) Copper - Lead Solder (CS) Galvanized (G) Galvanized Requiring Replacement (GR) Lead (L) Cast/Ductile Iron or Titanium (D) Plastic - PVC, HDPE, PEK (P) Unknown (U) Unknown Not Lead (UNL)	Galvanized Requiring Replacement (GR) Unknown (U) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Titanium (D) Plastic - PVC, HDPE, PEK (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a lead section, mark this (Y). If the galvanized service line material was never downstream of any lead section, mark this (N). If Yes, what section of service line should be marked as Galvanized Requiring Replacement (the appropriate immediately preceding column).	Enter date customer was notified of lead service line. If Service Line is not lead put N/A	Yes (Y) or No (N)	If previous column was marked (Y), provide date the lead service line was replaced. Leave blank if previous column was (N). Cast/Ductile Iron or Titanium (D) Plastic - PVC, HDPE, PEK (P) Leave blank if no Lead Service Line was replaced.	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEK (P) Cast/Ductile Iron or Titanium (D) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date notice obtained by PWS or date PWS notified DSH of refusal to sign waiver. Leave blank if customer had not refused access.
1 MOSELY DRIVE	N/A	N	N			installation date was after the lead ban per aerial photo	UNL	C	UNL	NL	N	N/A	N			N		
10 DACHARY CT	N/A	N	N			Visual Inspection	UNL	C	U	U	N	N/A	N			N		
1000 S 5TH	N/A	N	N			Visual Inspection	UNL	C	U	U	N	N/A	N			N		
1001 S 6TH	N/A	N	N			Visual Inspection	UNL	C	U	U	N	N/A	N			N		
1000 S 5TH	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
1000 W CENTER	N/A	N	N			Visual Inspection	UNL	C	P	NL	N	N/A	N			N		
1023 S 5TH	N/A	N	N			Visual Inspection	UNL	C	U	U	N	N/A	N			N		
1025 W CENTER	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
1036 W NORTH	N/A	N	N			Visual Inspection	UNL	D	D	NL	N	N/A	N			N		
1022 CENTER	N/A	N	N			Visual Inspection	UNL	C	P	NL	N	N/A	N			N		
102 N BERGMAN	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
102 S 3RD	N/A	N	N			Customer Survey and Visual Inspection	UNL	C	U	U	N	N/A	N			N		
1024 W NORTH	N/A	N	N			Visual Inspection	UNL	D	D	NL	N	N/A	N			N		
1025 W NORTH	N/A	N	N			Customer Survey and Visual Inspection	UNL	C	U	U	N	N/A	N			N		
1020 W CENTER	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
1023 Buffalgr	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
1013 S 7TH	N/A	N	N			Visual Inspection	UNL	C	U	U	N	N/A	N			N		
1013 W MILL	N/A	N	N			Visual Inspection	UNL	C	P	NL	N	N/A	N			N		
1010 W CENTER	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
104 N MCKINLEY	N/A	N	N			Visual Inspection	UNL	C	U	U	N	N/A	N			N		
104 N SECTION	N/A	N	N			Visual Inspection	UNL	C	U	U	N	N/A	N			N		
104 W MOUND	N/A	N	N			Visual Inspection	UNL	C	P	NL	N	N/A	N			N		
1040 W NORTH	N/A	N	N			Customer Survey and Visual Inspection	UNL	C	U	U	N	N/A	N			N		
1025 Buffalgr	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
101 E NORTH	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
1015 S 8TH	N/A	N	N			Visual Inspection	UNL	C	U	U	N	N/A	N			N		
1015 W NORTH	N/A	N	N			Visual Inspection	UNL	C	UNL	NL	N	N/A	N			N		
1010 W CENTER	N/A	N	N			Visual Inspection	UNL	C	U	U	N	N/A	N			N		
1066 W SOUTH	N/A	N	N			Visual Inspection	UNL	C	P	NL	N	N/A	N			N		
107 S 2ND	N/A	N	N			Customer Survey and Visual Inspection	UNL	C	U	U	N	N/A	N			N		
1075 W NORTH	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
108 N HARRISON	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
108 W CENTER	N/A	N	N			Visual Inspection	UNL	C	U	U	N	N/A	N			N		
1085 W CENTER	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
109 Buffalgr	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
109 S MILL	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
109 E NORTH	PL4204	N	N			Visual Inspection	UNL	C	P	NL	N	N/A	N			N		
109 N WILSON	N/A	N	N			Visual Inspection	UNL	C	P	NL	N	N/A	N			N		
109 S 5TH	N/A	N	N			Visual Inspection	UNL	C	P	NL	N	N/A	N			N		
109 W MILL	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
1096 W SOUTH	N/A	N	N			installation date was after the lead ban per aerial photo	UNL	C	UNL	NL	N	N/A	N			N		
110 LIBERTY	N/A	N	N			Visual Inspection	UNL	C	U	U	N	N/A	N			N		
110 W MCKINLEY	N/A	N	N			Visual Inspection	UNL	C	P	NL	N	N/A	N			N		
111 N HARRISON	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
111 W WILSON	N/A	N	N			Visual Inspection	UNL	C	P	NL	N	N/A	N			N		
111 W WASHINGTON	N/A	N	N			Visual Inspection	UNL	C	U	U	N	N/A	N			N		
1111 S 6TH	N/A	N	N			Visual Inspection	UNL	C	P	NL	N	N/A	N			N		
112 N 1ST	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
112 S 4TH	N/A	N	N			Visual Inspection	UNL	C	P	NL	N	N/A	N			N		
112 N WILSON	N/A	N	N			Visual Inspection	UNL	C	P	NL	N	N/A	N			N		
112 RACHEL ROAD	N/A	N	N			Visual Inspection	UNL	C	UNL	NL	N	N/A	N			N		
112 SHADY LN	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
112 W CENTER	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
112 W NORTH	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
113 Buffalgr	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
113 N 2ND	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
113 N WILSON	N/A	N	N			Visual Inspection	UNL	C	U	U	N	N/A	N			N		
113 W MCKINLEY	N/A	N	N			Visual Inspection	UNL	C	U	U	N	N/A	N			N		
114 N HARRISON	N/A	N	N			Visual Inspection	UNL	C	U	U	N	N/A	N			N		
114 N LINCOLN	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
114 N MCKINLEY ST	N/A	N	N			Visual Inspection	UNL	C	UNL	NL	N	N/A	N			N		
114 N SHERMAN	N/A	N	N			Visual Inspection	UNL	C	P	NL	N	N/A	N			N		
114 SHADY LN	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
114 W MCKINLEY	N/A	N	N			Visual Inspection	UNL	C	P	NL	N	N/A	N			N		
114 W MOUND E water	N/A	N	N			Visual Inspection	UNL	C	UNL	NL	N	N/A	N			N		
114 W MOUND W water	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
114 W NORTH	N/A	N	N			Visual Inspection	UNL	C	U	U	N	N/A	N			N		
115 Buffalgr	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
115 E MCKINLEY	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
115 LIBERTY COURT	N/A	N	N			Visual Inspection	UNL	C	U	U	N	N/A	N			N		
115 N 1ST	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
115 N LINCOLN	N/A	N	N			Visual Inspection	UNL	C	U	U	N	N/A	N			N		
115 N SHERMAN	N/A	N	N			Visual Inspection	UNL	C	U	U	N	N/A	N			N		
115 S 2ND	N/A	N	N			Customer Survey and Visual Inspection	UNL	C	UNL	NL	N	N/A	N			N		
115 S 6TH	N/A	N	N			Visual Inspection	UNL	C	C	NL	N	N/A	N			N		
115 W MOUND	N/A	N	N			Visual Inspection	UNL	C	P	NL	N	N/A	N			N		

